



AEROSEAL

## Case Study

MEZ-AEROSEAL

# Restaurant Paragraph

» *Elimination of odour nuisance through improved tightness of duct work.* «

# Restaurant Paragraph

**Location:** Rapperswil, Switzerland

**Date:** October 2015

**MEZ-AEROSEAL Partner:** MEZ-TECHNIK GmbH

**Executing company:** -

**Result:** The riser duct of the kitchen exhaust was cleaned first. This made sealing with MEZ-AEROSEAL a really easy task, since the sealant could adhere to the leakage without problems. The kitchen exhaust duct was sealed 100 %. The odour nuisance could be completely eliminated.



Smell



Noise



Energy efficiency



Air tightness



Indoor air quality

## Description

The kitchen exhaust duct of the Swiss traditional restaurant „Paragraph“ was causing odour nuisance in the apartments above. Manual sealing efforts were not an option due to limited access to the duct work. Thus, the only possible solution was to seal the duct with MEZ-AEROSEAL.

## Successful sealing

With our successful MEZ-AEROSEAL partner network we achieve great success again and again.

## The change in leakages

### Before sealing

- 10 l/s

### After sealing

- 0 l/s

### Reduction

- 100%



[www.mez-technik.com](http://www.mez-technik.com)



[info@mez-technik.de](mailto:info@mez-technik.de)



+49 (7072) 600980